



ecology and environment, inc.

108 SOUTH WASHINGTON, SUITE 302, SEATTLE, WASHINGTON 98104, TEL. 206-624-9537

International Specialists in the Environmental Sciences

MEMORANDUM

DATE: September 5, 1985
TO: John Roland, E&E, Seattle
FROM: Jim Braddock, E&E, Seattle JB
SUBJ: Disposal of Drilling - Derived Wastes and Other Wastes
Produced at Greenacres Landfill, Spokane, WA
REF: TDD R10-8408-44

In a meeting attended by Neil Thompson, Rene Fuentes of USEPA - Region X, and Jim Braddock on September 5, 1985, results of analyses of well samples from three wells drilled on-site as well as one off-site private well were presented. Thompson and Fuentes concluded that the levels of substances detected were too low to consider the drummed wastes hazardous and the following should be done:

- 1) Spill the liquids and drill cuttings onto the existing exposed pile of refuse (which, according to John Roland, is now covered with topsoil).
- 2) Place dry solid wastes in large plastic bags and dispose of at Mica Landfill near Spokane.
- 3) Steam clean drums either at site or at Liberty Lake Water District Sewage Plant.

Thompson and Fuentes also conclude that no further tests be performed on the materials in the drums. The drums may be kept for future use.

A memo will be issued by Thompson through Fuentes to Roland in the next few days.

JB:jkb

